ਦਫ਼ਤਰ : ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਮਾਨਸਾ।

ਟੈਲੀਫੋਨ/ਫੈਕਸ ਨੰ: 01652-232119 Email ID :- xen.mansa@gmail.com

ਪੱਤਰ ਨੰ. 748 ਮਿਤੀ 09/05/2024

ਵੱਲ,

Principal

Sh. Tara Chand Vidya mandir Sr. Sec. School

Bhikhi (Mansa).

ਵਿਸ਼ਾ: ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ। (ਸਾਲ 2024-25)

ਹਵਾਲਾ: ਆਪ ਦਾ ਰੈਫ ਨੰ. T.C.V.M/2024-25/4194 ਮਿਤੀ 22/04/2024 ਦੇ ਸਬੰਧ ਵਿੱਚ।

ਤੁਹਾਡੇ ਸਕੂਲ ਬਿਲਡਿੰਗ ਦੀ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਦੇ ਦਫਤਰ ਵੱਲੋਂ ਵਿਜ਼ੂਅਲੀ ਇੰਸਪੈਕਸ਼ਨ ਕੀਤੀ ਗਈ ਅਤੇ ਉਹਨਾਂ ਦੀ ਰਿਪੋਰਟ/ਸ਼ਿਫਾਰਿਸ਼ ਅਨੁਸਾਰ ਨਿਮਨਲਿਖਤ ਨਿਰੀਖਣਾਂ ਅਤੇ ਸ਼ਰਤਾਂ ਅਧੀਨ ਸਾਲ 2024-25 ਦਾ ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਮਿਤੀ 31-03-2025 ਤੱਕ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ:-

1) ਸ਼੍ਰੀ ਦਰਸ਼ਨ ਪਾਲ ਜਿੰਦਲ ਦੁਆਰਾ ਮਿਤੀ 12-04-2024 ਨੂੰ ਸਟਰੱਕਚਰ ਸੁਰੱਖਿਆ ਸਰਟੀਫਿਕੇਟ ਦਿੱਤਾ ਗਿਆ ਹੈ ਅਤੇ ਉਹਨਾਂ ਦੇ ਸਰਟੀਫਿਕੇਟ ਅਨੁਸਾਰ ਸਕੂਲ ਸੈਸ਼ਨ 2024-25 ਲਈ ਵਰਤੋਂ ਲਈ ਸੁਰੱਖਿਅਤ ਹੈ, ਪਰੰਤੂ ਇਸ ਸਕੂਲ ਦਾ ਨਿਰਮਾਣ ਇਸ ਵਿਭਾਗ ਵੱਲੋਂ ਨਹੀਂ ਕੀਤਾ ਗਿਆ ਹੈ, ਇਸ ਲਈ ਇਸ ਵਿਭਾਗ ਦੁਆਰਾ ਸਕੂਲ ਦੇ ਸਟਰੱਕਚਰ ਦੀ ਸੇਫਟੀ ਖਾਸ ਕਰਕੇ ਭੂਚਾਲ ਦੇ ਦ੍ਰਿਸ਼ਟੀਕੋਣ ਤੋਂ ਯਕੀਨੀ ਨਹੀਂ ਬਣਾਈ ਜਾ ਸਕਦੀ ਹੈ।

2) ਜੇਕਰ ਸਕੂਲ ਵੱਲੋਂ ਇਸ ਇਮਾਰਤ ਵਿੱਚ ਕੋਈ ਵਾਧਾ, ਤਬਦੀਲੀ, ਵਿਸਤਾਰ ਅਤੇ ਸੋਧ ਦੀ ਲੋੜ ਹੈ ਜਾਂ ਕੀਤੇ ਜਾਣੇ ਹਨ ਤਾਂ ਇਸ ਦਫਤਰ ਦੀ ਤੁਰੰਤ ਜਾਂਚ ਦਾ ਪ੍ਰਬੰਧ ਕੀਤਾ ਜਾਣਾ ਚਾਹੀਦਾ ਹੈ ਅਤੇ ਉਸ ਹਿੱਸੇ ਨੂੰ ਮੁਕੰਮਲ ਕਰਕੇ ਉਸ ਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਇਸ ਦਫਤਰ ਪਾਸੋਂ ਫਿਰ ਤੋਂ ਲਿਆ ਜਾਵੇ।

3) ਜੇਕਰ ਬਿਲਡਿੰਗ ਦੀਆਂ ਕੰਧਾ, ਨੀਹਾਂ ਅਤੇ ਛੱਤਾਂ ਕੁਦਰਤੀ ਆਫਤ ਜਾਂ ਕਿਸੇ ਹੋਰ ਕਾਰਨ ਕਰਕੇ ਬੈਠ ਜਾਣ ਤਾਂ ਇਸ ਸੂਰਤ ਵਿੱਚ ਸਕੂਲ ਵੱਲੋਂ ਇਸ ਦਫਤਰ ਨੂੰ ਤੁਰੰਤ ਬਿਲਡਿੰਗ ਦੀ ਹਾਲਤ ਬਾਰੇ ਸੂਚਿਤ ਕੀਤਾ ਜਾਵੇ ਅਤੇ ਨਿਰੀਖਣ ਕਰਵਾਉਣ ਉਪਰੰਤ ਹੀ ਬਿਲਡਿੰਗ ਨੂੰ ਵਰਤੋਂ ਵਿੱਚ ਲਿਆ ਜਾਵੇ।

4) ਸਬੰਧਤ ਵਿਭਾਗ ਤੋਂ ਵੱਖਰੇ ਤੌਰ ਤੇ ਫਾਇਰ ਸੇਫਟੀ ਅਤੇ ਬਿਜਲੀ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਪ੍ਰਾਪਤ ਕੀਤਾ ਜਾਵੇ।

5) ਸਕੂਲ ਬਿਲਡਿੰਗ ਦੀ ਸੇਫਟੀ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਬਿਲਡਿੰਗ ਦੀ ਰਿਪੇਅਰ ਕਰਵਾਉਣ ਦੀ ਜ਼ਿੰਮੇਵਾਰੀ ਸਕੂਲ ਪ੍ਰਬੰਧਨ ਦੀ ਹੈ। ਇਸ ਰਿਪੋਰਟ ਦੇ ਬਾਵਜੂਦ ਸਕੂਲ ਪ੍ਰਬੰਧਨ ਸਾਰੇ ਪੱਖਾਂ ਤੋਂ ਬਿਲਡਿੰਗ ਦੀ ਸੁਰੱਖਿਆ ਲਈ ਜ਼ਿੰਮੇਵਾਰ ਹੈ।

6) ਸਕੂਲ ਕੋਲ ਕਿਸੇ ਅਣਸੁਖਾਵੀਂ ਆਪਦਾ ਨਾਲ ਨਜਿੱਠਣ ਲਈ ਯੋਜਨਾ ਹੋਣੀ ਚਾਹੀਦੀ ਹੈ, ਜਿਸ ਵਿੱਚ ਐਮਰਜੈਂਸੀ ਦੌਰਾਨ ਬੱਚਿਆਂ ਨੂੰ ਬਿਲਡਿੰਗ ਵਿਚੋਂ ਸੁਰਖਿਅਤ ਬਾਹਰ ਕੱਢਣਾ ਅਤੇ ਸਬੰਧਤ ਵਿਭਾਗ ਨਾਲ ਤਾਲਮੇਲ ਕਰਨ ਦੀ ਯੋਜਨਾ ਹੋਣੀ ਚਾਹੀਦੀ ਹੈ। ਸਕੂਲ ਨੂੰ ਇਸ ਯੋਜਨਾ ਦੀ ਪ੍ਰਭਾਵਸ਼ੀਲਤਾ ਨੂੰ ਯਕੀਨੀ ਬਣਾਉਣ ਲਈ ਨਿਯਮਿਤ ਤੌਰ 'ਤੇ ਸਮੀਖਿਆ ਅਤੇ ਅੱਪਡੇਟ ਕਰਦੇ ਰਹਿਣਾ ਚਾਹੀਦਾ ਹੈ।

7) ਪੰਜਾਬ ਸਰਕਾਰ ਦੀਆਂ ਹਦਾਇਤਾਂ ਮੁਤਾਬਕ ਰੋਡ ਟੂ ਅਸੈਸ ਦੀ ਮੰਨਜੂਰੀ ਸਬੰਧਤ ਵਿਭਾਗ ਤੋਂ ਲੈਣ ਲਈ ਸਕੂਲ ਪ੍ਰਬੰਧਕ ਖੁਦ ਜ਼ਿੰਮੇਵਾਰ ਹੋਵੇਗਾ।

8) ਸਕੂਲ ਨੂੰ ਸਟਾਫ਼ ਮੈਂਬਰਾਂ ਨੂੰ ਉਚਿਤ ਸੁਰੱਖਿਆ ਸਿਖਲਾਈ ਪ੍ਰਦਾਨ ਕਰਨੀ ਚਾਹੀਦੀ ਹੈ, ਜਿਸ ਵਿੱਚ ਐਮਰਜੈਂਸੀ, ਫਸਟ ਏਡ ਅਤੇ ਨਿਕਾਸੀ ਪ੍ਰੋਟੋਕੋਲ ਨੂੰ ਸੰਭਾਲਣ ਦੀਆਂ ਪ੍ਰਕਿਰਿਆਵਾਂ ਵੀ ਸ਼ਾਮਲ ਹਨ।

9) ਸਕੂਲ ਦੇ ਕਵਰਡ ਏਰੀਏ ਦੇ ਹਿਸਾਬ ਨਾਲ ਜੀ.ਆਰ ਨੰ. 2843895 ਮਿਤੀ: 30-04-2024 ਰਾਹੀਂ ਦਸ ਹਜ਼ਾਰ ਰੁਪਏ (10,000/-) ਬਿਲਡਿੰਗ ਨਿਰੀਖਣ ਫੀਸ ਵਜੋਂ ਪ੍ਰਾਪਤ ਕੀਤੇ ਗਏ।

10) ਇਹ ਰਿਪੋਰਟ ਕਾਨੂੰਨੀ ਉਦੇਸ਼ ਲਈ ਵੈਲਿਡ ਨਹੀਂ ਹੈ।

ਨੱਥੀ: ਨਕਸ਼ਾ

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਮਾਨਸਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰ. ਮਿਤੀ

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ, ਬੁਢਲਾਡਾ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰ. 83 ਮਿਤੀ 09/05/2024 ਦੇ ਸਬੰਧ ਵਿੱਚ ਭੇਜ ਕੇ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਆਪ ਦੀ ਸਿਫਾਰਿਸ਼ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਉਕਤ ਸਕੂਲ ਨੂੰ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਮਾਨਸਾ।

Scanned with OKEN Scanner
Scanned with OKEN Scanner

TO

Principal
Sh.Tara Chand Vidya mandir Sr. Sec. School
Bhikhi (Mansa).

NOTARY
Manoj Kumar
Distt. MANSA
Regd. No.
13216
GOVT. OF INDIA

SUBJECT: Regarding issuing building safety certificate. (Year 2024-25)

Reference: Ref. No. 8. T.C.V.M/2024-25/4194 dated 22/04/2024.

Your school building was visually inspected by the office of the Sub Divisional Engineer and School Building Safety for the year 2024-25 under the following observations and conditions as per the report/recommendation of Certificate Date 31-03-2025: -

1) Structure Safety Certificate has been granted by Shri Darshan Pal Jindal on 12-04-2024 and he According to the certificate of the school is safe to use for the session 2024-25, but the construction of this school is not made under the control of this department. Therefore, this department doesn't ensure the safety of the school structure especially in case of earthquake. Cannot be ascertained from perspective.

2) If any addition, alteration, expansion and modification is required or has to be made by the school in this building. Arrangements should be made for immediate inspection of this office and the safety of that part should be completed. The certificate should be obtained again from this office.

3) If the walls, foundations and roofs of the building sink due to natural calamity or any other reason, then in this case the school should immediately inform this office about the condition of the building and get an after inspection the building should be used.

4) Fire safety and electrical safety certificates should be obtained separately from the concerned department.

5) It is the responsibility of the school management to get the building repaired keeping in mind the safety of the school building. Despite this report, the school management is responsible for the safety of the building from all aspects.

6) The school should have a plan to deal with any unexpected disaster, including during an emergency. There should be a plan to get children out of the building safely and to coordinate with the concerned department. The school should regularly review and update the plan to ensure its effectiveness.

7) As per the instructions of the Punjab Government, the school administrator will be responsible for taking approval for road to access from the concerned department.

8) The school must provide appropriate safety training to staff members, including emergency, first aid and withdrawal protocols are also included.

Certified to be true translation from
Punjabi Hindi/Urdu into English

(MANOJ KUMAR)
NOTARY (Govt. of India)
Distt. MANSA (Pb.)

Scanned with OKEN Scanner

9) According to the covered area of the school, G.R. No. 2843895 Dated: 30-04-2024 Ten Thousand Rupees (10,000/-) received as building inspection fee.

NOTARY
Manoj Kumar
Distt. MANSA
Regd. No.
13216
GOVT. OF INDIA

10) This report is not valid for legal purposes.
Name:

Executive Engineer,
Provincial Division B&M Branch,
Mansa.

Back number no. DATE

The above is excerpted from his letter no. to the Sub Divisional Engineer, Provincial Sub Division, Budhlada. Regarding 83 dated 09/05/2024, it is written that keeping your recommendation in mind, the said school Building Safety Certificate is issued

Executive Engineer,
Provincial Division B&M Branch,
Mansa.

Certified to be true translation from
Punjabi Hindi/Urdu into English

(MANOJ KUMAR)
NOTARY (Govt. of India)
Distt. MANSA (Pb.)

Scanned with OKEN Scanner