## BUILDING SAFETY CERTIFICATE

No. 692			Date	d: 21/05/25
Certified that th	e existing building	Sh. Tana chand by Sen sec. sc	gya Maxtor	(name of the
building or premi	ses) at ይኒኒኒኒኒ (address) cor	ትላ አደር፡ የc ፕረካ <u> </u>	mansa CPI	ე გ. გ. გ. გ. basement(s) and
I Blode	, and Block	19 Mantu sen s	pper floors) ow	ned/occupied by
		(name of the In	1.50	
Building safety	requirements in acc	ordance with National E	Building code Rule	s, and verified by
the officers on 915	concerned of Bock	inspection) p w s	(Name of De Manua in the	partment/ Govt:) presence of
,	_	pe		
Manager/Secre	tary or his represe	ntative) and that the bu	ilding/premises is	fit for occupancy
upto classes	I	(X/ XII) with effect from	om. 0.1.14.1.25	for a period of
		dance with rule and su		
conditions as a	ppended.	re Salety Certific		

2. It is the Responsibility of the school Management to get the Builting Repair to. 3. The school smust provide appropriate Salety Training to Statt members 4. The school should rejularly services and ablate the plan to ensure its issued on 21/5/25 at Bhithic Manna) by effective effectivener

Signature with Seal Designationansa Name & Address of Department/ Office: (Assistant Engineer & above officer of concerned Govt. Department only)

Note: This certificate should be signed / issued by Assistant Engineer & above officer of concerned Goyt. Department only

<sup>\*</sup> Strike out whichever is not applicable.

<sup>\*</sup> The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.